

**APPENDIX
C**

STANDARD OPERATING PROCEDURES

CONTENTS

- SOP 1. Field Screening
- SOP 2. Surface and Subsurface Soil Sampling
- SOP 3. Monitoring Well Design and Installation
- SOP 4. Monitoring Well Sampling
- SOP 5. Monitoring Well and Test-Hole Abandonment
- SOP 6. Quality Assurance/Quality Control Samples
- SOP 7. Sample Preservation, Storage, Handling and Documentation
- SOP 8. Sampling Equipment Decontamination
- SOP 9. Drilling Methods
- SOP 10. On-Site Staging and Storage of Contaminated Soil
- SOP 11. General Air sampling Guidelines
- SOP 12. Air Permeability Test
- SOP 13. In Situ respiration Test
- SOP 14. In-Situ Permeability Testing