

Examples of Bus Disposal Pictures

Photo #1: Side profile of bus being scrapped



Sideprofile.jpeg

Photo #2: VIN of the bus being scrapped



VIN.jpeg

Photo #3: Engine tag with engine serial number and EPA engine family name



Enginetag.jpeg

Photo #4: Chassis rail cut in half



Chassis.jpeg

Photo #5: Engine block prior to hole being drilled



Engineblockprior.jpeg

Photo #6: Engine block after hole has been drilled



Engineblockafter.jpeg