

Guadalajara Mexican Restaurant Drinking Water Information

(System Information, Sampling Requirements, and Compliance Report)



2017 Certificate of Achievement Award.

Population Served:	300	System Population:	300
Certified Operator:	Mr Mike Kyte 1221 N Main Spearfish, SD 57783	Work Phone:	(605)645-1276
		Home Phone:	(605)642-4932
		Cell Phone:	
		Fax:	
		Email:	mwkyte@spe.midco.net
Financial Contact:	Mr Dagoberto Rodriguez 83 W Highway 14 Spearfish, SD 57783	Work Phone:	(605)642-7383
		Home Phone:	
		Cell Phone:	
		Fax:	
		Email:	
Other Contacts:			
Last Inspection:	September 12, 2017		
Type of System:	Non-Community	Area Served:	Lawrence County
Number of Service Connections:	420	Contamination Risk:	low
Water Produced And Used By The Guadalajara Mexican Restaurant Public Water System			
PWS Owner Type:	Private Ownership	Service Area:	Restaurant
Contract Laboratory:			Midcontinent Laboratory

Violations and Significant Deficiencies

Guadalajara Mexican Restaurant

EPA ID: 0568

Violations From **January 1, 2013** To **January 1, 2018**

Violation Type	Parameter	Date	Status
Exceedance of Allowable Contaminant Level	Total Coliform Bacteria	04/01/2015	Public Notice Requested
	Bacteriological		Compliance Achieved
	Bacteriological		Public Notice Received

Significant Deficiency	Date Identified	Date Corrected

EPA ID#: 0568 System Name: Guadalajara Mexican Restaurant

Sampler- Mr Mike Kyte Work Phone-(605)645-1276
Title- Certified Operator
Address- 1221 N Main
Spearfish SD 57783

Location- City: Spearfish County: Lawrence
Service Area- Restaurant
PWS Owner Type- Private Ownership
Water Supply Type- Groundwater Supply

Population Served- 300 Service Connections- 1

Months that System is Open to Public-Season Opening Date- January 1st Season Closing Date- December 31st

Sources for Guadalajara Mexican Restaurant

Source	Name	Year Built	Depth (feet)	Diameter (inches)	Availability	Type	Vulnerability	Treatment
01	TREAT SITE - #1				Permanent	Treatment Plant	Non-Vulnerable	Disinfection - Hypochlorites Filtration - Zeolite
04	#1	1953	40	4	Permanent	Groundwater	Vulnerable	Treatment At Plant

EPA ID#: 0568 System Name: Guadalajara Mexican Restaurant

Common Ion Data

(All chemical data are reported in milligrams per liter (mg/l) except pH and Langlier Index)

Please refer to Private Well Data for more information about these test results.

Source	Type	Date	TDS	Conductance	pH	Alk-M	Alk-P	Na	K	Ca	Mg	Fe	Mn	Cl	SO4	HCO3	CO3	Hardness	Langlier	NO3	F
01	Raw	01/23/91	0	0	0.00	0	0	0	0.0	0.0	0.0	0.00	0.00	0.0	0	0	0	0	0.00	0.9	0.00

Source	Type	Date	TDS	Conductance	pH	Alk-M	Alk-P	Na	K	Ca	Mg	Fe	Mn	Cl	SO4	HCO3	CO3	Hardness	Langlier	NO3	F
01	Treated	10/22/97	0	0	0.00	0	0	0	0.0	0.0	0.0	0.00	0.00	0.0	40	0	0	0	0.00	1.6	0.00