

Saint Onge Livestock Cafe Drinking Water Information

(System Information, Sampling Requirements, and Compliance Report)



2017 Certificate of Achievement Award.

Population Served:	30	System Population:	30
Certified Operator:	Mr Mike Kyte 1221 N Main Spearfish, SD 57783	Work Phone:	
		Home Phone:	
		Cell Phone:	
		Fax:	
		Email:	mwkyte@spe.midco.net
Financial Contact:	Ms Brooke Tupper PO Box 290 St Onge, SD 57779-0290	Work Phone:	(605)642-2200
		Home Phone:	
		Cell Phone:	
		Fax:	
		Email:	stonge@rushmore.com
Other Contacts:	Ms Ashley Jensen PO Box 290 St Onge, SD 57779-0290	Work Phone:	(605)642-2200
		Home Phone:	
		Cell Phone:	
		Fax:	
		Email:	
Last Inspection:	September 12, 2017		
Type of System:	Non-Community	Area Served:	Lawrence County
Number of Service Connections:	100	Contamination Risk:	low
Water Produced And Used By The Saint Onge Livestock Cafe Public Water System			
PWS Owner Type:	Private Ownership	Service Area:	Restaurant
Contract Laboratory:			Midcontinent Laboratory

Violations and Significant Deficiencies

Saint Onge Livestock Cafe

EPA ID: 1047

Violations From **January 1, 2013** To **January 1, 2018**

Violation Type	Parameter	Date	Status
Failure to Develop Sample Site Plan	RTCR	06/01/2016	Reminder Notice
	RTCR		Compliance Achieved

Significant Deficiency	Date Identified	Date Corrected