

Pactola Pines Store Drinking Water Information

(System Information, Sampling Requirements, and Compliance Report)

This system is not a candidate for an award:

Violation , Operator Certification Not Required

Population Served:	35	System Population:	35
Certified Operator:	Mr Dave Fisher 23060 Custer Gulch Road Rapid City, SD 57702	Work Phone:	(605)343-4283
		Home Phone:	(605)341-5511
		Cell Phone:	
		Fax:	
		Email:	nancy@pactolapines.com
Financial Contact:	Ms Nancy Fisher 23060 Custer Gulch Road Rapid City, SD 57702	Work Phone:	(605)343-4283
		Home Phone:	(605)341-5511
		Cell Phone:	
		Fax:	
		Email:	
Other Contacts:	Mr Brian Beam 25041 N Hwy 16 Custer, SD 57730	Work Phone:	
		Home Phone:	
		Cell Phone:	
		Fax:	
		Email:	
Last Inspection:	June 1, 2017		
Type of System:	Non-Community	Area Served:	Pennington County
Number of Service Connections:	21	Contamination Risk:	moderate
Water Produced And Used By The Pactola Pines Store Public Water System			
PWS Owner Type:	Private Ownership	Service Area:	Recreation Area
Contract Laboratory:			Midcontinent Laboratory

Violations and Significant Deficiencies

Pactola Pines Store

EPA ID: 1069

Violations From January 1, 2013 To January 1, 2018

Violation Type	Parameter	Date	Status
Failure to Issue PN for Violation 00120	Public Notice	09/04/2016	
Failure to Issue PN for Violation 00119	Public Notice	09/04/2016	
Failure to Issue PN for Violation 00121	Public Notice	10/13/2015	
Exceedance of Allowable Contaminant Level	Total Coliform Bacteria	08/01/2015	Public Notice Requested
	Bacteriological		DENR Issued PN
	Bacteriological		Compliance Achieved
	Bacteriological		Public Notice Received
Failure to Take Source Samples	E. Coli	08/29/2015	Public Notice Requested
	E. Coli		DENR Issued PN
	E. Coli		Public Notice Received
Failure to Take Source Samples	E. Coli	08/29/2015	Public Notice Requested
	E. Coli		DENR Issued PN
	E. Coli		Public Notice Received

Significant Deficiency	Date Identified	Date Corrected