

EPA ID#: 1109 System Name: Broken Arrow C Bar and Supper Club

Sampler- Mr Samuel Claymore Work Phone-(605)823-4406
Title- Broken Arrow C
Address- HC 79 Box 231
McLaughlin SD 57642

Location- City: MclaughlinCounty: Corson
Service Area- Restaurant
PWS Owner Type- Private Ownership
Water Supply Type- Groundwater Supply

Population Served- 25 Service Connections- 1

Months that System is Open to Public-Season Opening Date- January 1st Season Closing Date- December 31st

Sources for Broken Arrow C Bar and Supper Club

| Source | Name | Year Built | Depth (feet) | Diameter (inches) | Availability | Type | Vulnerability | Treatment |
|--------|-----------------|------------|--------------|-------------------|--------------|-----------------|----------------|------------------------------|
| 01 | TREAT SITE - #1 | | | | Permanent | Treatment Plant | Non-Vulnerable | Disinfection - Hypochlorites |
| 03 | #1 | 1964 | 90 | 5 | Permanent | Groundwater | Vulnerable | No Treatment |

EPA ID#: 1109 System Name: Broken Arrow C Bar and Supper Club

Common Ion Data

(All chemical data are reported in milligrams per liter (mg/l) except pH and Langlier Index)

Please refer to Private Well Data for more information about these test results.

| Source | Type | Date | TDS | Conductance | pH | Alk-M | Alk-P | Na | K | Ca | Mg | Fe | Mn | Cl | SO4 | HCO3 | CO3 | Hardness | Langlier | NO3 | F |
|--------|---------|----------|-----|-------------|------|-------|-------|----|-----|-----|-----|------|------|-----|-----|------|-----|----------|----------|-----|------|
| 01 | Treated | 10/28/92 | 0 | 0 | 0.00 | 0 | 0 | 0 | 0.0 | 0.0 | 0.0 | 0.00 | 0.00 | 0.0 | 0 | 0 | 0 | 0 | 0.00 | 1.4 | 0.00 |