

Public Record

(Required by the Energy Policy Act of 2005)

Summary Information On Regulated Underground Storage Tanks (USTs)

General Summary

Total number of existing regulated UST facilities 1000
 Total number of existing USTs 3009

Summary Information For On-Site Inspections

Number of facilities inspected 380
 Inspection period dates 10/01/2008 To 09/30/2009
 Percent compliance 59%

(On-site inspections measure compliance with release detection and release prevention)

Summary Information For Releases

Number of confirmed UST releases 21
 Release reporting period dates 10/01/2008 To 09/30/2009

Summary Information For Release Sources And Causes

Source			Cause													
			Spill		Overfill		Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	3	14%			1	33%			2	67%						
Piping																
Dispenser																
STP																
Delivery Problem																
Other	5	24%											5	100%		
Unknown	13	62%													13	100%
Totals	21	100%			1	4.7%			2	9.5%			5	23.8%	13	62%

Notes:

- 1) # = number
- 2) % = percent of total number (each Source % is calculated by dividing each source # by the Source Total. Each Cause % is calculated by dividing each Cause # by the Source #)
- 3) Source and Cause data were collected from release reported to the Department during the time period of the report.
- 4) Unknown = Release discovered during tank removal or pre-buy assessment.
- 5) Other = is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs and releases may be obtained by calling (605) 773-3296 or by visiting our web site at <http://denr.sd.gov/des/gw/Spills/SpillData.aspx>