

## Public Record

(Required by the Energy Policy Act of 2005)

### Summary Information On Regulated Underground Storage Tanks (USTs)

#### General Summary

Total number of existing regulated UST facilities ..... 981  
 Total number of existing USTs ..... 3084

#### Summary Information For On-Site Inspections

Number of facilities inspected ..... 424  
 Inspection period dates ..... 01/01/2010 To 12/31/2010  
 Percent compliance ..... 67.2%

(On-site inspections measure compliance with release detection and release prevention)

#### Summary Information For Releases

Number of confirmed UST releases ..... 17  
 Release reporting period dates ..... 01/01/2010 To 12/31/2010

#### Summary Information For Release Sources And Causes

Source			Cause														
			Spill		Overfill		Damage		Corrosion		Install Problem		Other		Unknown		
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%	
Tank	11	64.7%			2	18.2%			9	81.8%							
Piping	2	11.8%													2	100%	
Dispenser																	
STP																	
Delivery Problem																	
Other	2	11.8%											2	100%			
Unknown	2	11.8%													2	100%	
<b>Totals</b>	<b>17</b>	<b>100%</b>			<b>2</b>	<b>11.8%</b>			<b>9</b>	<b>52.9%</b>			<b>2</b>	<b>11.8%</b>	<b>4</b>	<b>23.5%</b>	

**Notes:**

- 1) # = number
- 2) % = percent of total number (each Source % is calculated by dividing each source # by the Source Total. Each Cause % is calculated by dividing each Cause # by the Source #)
- 3) Source and Cause data were collected from release reported to the Department during the time period of the report.
- 4) Unknown = Release discovered during tank removal or pre-buy assessment.
- 5) Other = is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs and releases may be obtained by calling (605) 773-3296 or by visiting our web site at <http://denr.sd.gov/des/gw/Spills/SpillData.aspx>