

## Public Record

(Required by the Energy Policy Act of 2005)

### Summary Information For Regulated Underground Storage Tanks (USTs)

#### General Summary

Total number of existing regulated UST facilities ..... 1029  
 Total number of existing USTs ..... 3028

#### Summary Information For On-Site Inspections

Number of facilities inspected ..... 435  
 Inspection period dates ..... 01/01/2019 to 12/31/2019  
 Percent compliance ..... 61%

(On-site inspections measure compliance with release detection and release prevention)

#### Summary Information For Releases

Number of confirmed UST releases ..... 40  
 Release reporting period dates ..... 01/01/2019 to 12/31/2019

#### Summary Information For Release Sources And Causes

Source			Cause													
			Spill		Overfill		Damage		Corrosion		Install Problem		Other		Unknown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
<b>Tank</b>	2	5%					1	17%	1	50%					10	59%
<b>Piping</b>	16	40%					2	33%					4	100%		
<b>Dispenser</b>	2	5%	2	100%												
<b>STP</b>	1	2.5%							1	50%						
<b>Delivery Problem</b>	11	27.5%			9	100%	2	33%								
<b>Other</b>	1	2.5%					1	17%								
<b>Unknown</b>	7	17.5%													7	41%
<b>Totals</b>	40	100%	2	5%	9	22.5%	6	15%	2	5%	0	0%	4	10%	17	42.5%

**Notes:**

- 1) # = number
- 2) % = percent of total number (each Source % is calculated by dividing each source # by the Source Total. Each Cause % is calculated by dividing each Cause # by the Source #)
- 3) Source and Cause data were collected from release reported to the Department during the time period of the report.
- 4) Unknown = Release discovered during tank removal or pre-purchase assessment.
- 5) Other = is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs and releases may be obtained by calling (605) 773-3296 or by visiting our web site at <http://denr.sd.gov/tanks>