

## Public Record

(Required by the Energy Policy Act of 2005)

### Summary Information For Regulated Underground Storage Tanks (USTs)

#### General Summary

Total number of existing regulated UST facilities ..... 1032  
 Total number of existing USTs ..... 3031

#### Summary Information For On-Site Inspections

Number of facilities inspected ..... 514  
 Inspection period dates ..... 10/01/2019 to 09/30/2020  
 Percent compliance ..... 73.3%

(On-site inspections measure compliance with release detection and release prevention)

#### Summary Information For Releases

Number of confirmed UST releases ..... 23  
 Release reporting period dates ..... 10/01/2019 to 09/30/2020

#### Summary Information For Release Sources And Causes

Source			Cause													
			Spill		Overfill		Damage		Corrosion		Install Problem		Other		Unknown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
<b>Tank</b>	3	13%							3	75%						
<b>Piping</b>	5	21.7%					3	75%							2	22.2%
<b>Dispenser</b>	4	17.4%	3	100%			1	25%								
<b>STP</b>	1	4.3%							1	25%						
<b>Delivery Problem</b>	2	8.7%			2	100%										
<b>Other</b>	1	4.3%											1	100%		
<b>Unknown</b>	7	30.4%													7	77.8%
<b>Totals</b>	23	100%	3	13%	2	8.7%	4	17.4%	4	17.4%	0	0%	1	4.3%	9	39.1%

**Notes:**

- 1) # = number
- 2) % = percent of total number (each Source % is calculated by dividing each source # by the Source Total. Each Cause % is calculated by dividing each Cause # by the Source #)
- 3) Source and Cause data were collected from release reported to the Department during the time period of the report.
- 4) Unknown = Release discovered during tank removal or pre-purchase assessment.
- 5) Other = is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs and releases may be obtained by calling (605) 773-3296 or by visiting our web site at <http://denr.sd.gov/tanks>